

Evaluation Agricultural Tractor - wheels		www.mevas.eu		
Customer:	<i>Mercier vendeville</i>	09-19		
Inspector:	<i>Jan beeckman</i>			
Machine / type:	<i>Claas Arion 640</i>	Hours/km:	<i>5618</i>	
Serial No. :	<i>A1934EAA1903429</i>	Year:	<i>2010</i>	
Date:	<i>04.10.2019</i>	Power (kW):	<i>129</i>	
CE: <input checked="" type="checkbox"/> air con. <input checked="" type="checkbox"/>	front PTO: <input type="checkbox"/>	Exterior controls:	<input checked="" type="checkbox"/> Cab suspension: <input checked="" type="checkbox"/>	
Front hyd.: <input type="checkbox"/>	Rear PTO: <input checked="" type="checkbox"/>	PTO <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/> PowerShift: <input checked="" type="checkbox"/>	
Rear hyd.: <input checked="" type="checkbox"/>	Trailer air brake sys: <input checked="" type="checkbox"/>	Hyd <input checked="" type="checkbox"/>		
cab		cab doors	<i>good</i>	
seat, arm rests	<i>cover needs cleaning</i>	windows, mirrors	<i>good</i>	
switches, levers	<i>good</i>	wipers, washer	<i>good</i>	
gauges, warn lights	<i>good</i>	floor mat	<i>good</i>	
aircon / heater	<i>operational</i>	cab structure	<i>good</i>	
engine		alternator / starter	<i>good</i>	
leaks & seals	<i>no leaks</i>	cooling system	<i>good</i>	
oil condition	<i>good</i>	blow by	<i>normal</i>	
exhaust	<i>good</i>	belts, filters	<i>good</i>	
smoke	<i>normal</i>	coolant condition	<i>good</i>	
exterior		sheet metal	<i>good</i>	
chassis, frames	<i>good</i>	fenders	<i>good</i>	
engine hood	<i>small damage on left side</i>	lights	<i>operational</i>	
stairs, hand rails	<i>good</i>	paintwork	<i>good</i>	
visual inspection				
PTO front/rear	<i>Rear PTO:</i>	Transmission leaks	<i>none</i>	
Hyd. Lines	<i>good</i>	Hyd cylinders:	<i>good</i>	
No. of circuits front	<i>0</i>	Frame	<i>good</i>	
No. of circuits rear	<i>5</i>	Rims	<i>good</i>	
functional test		Hydraulic functions	<i>good</i>	
PTO	<i>operational</i>	brake & park brake	<i>good</i>	
PTO rpm(s)	<i>540/1000</i>	Steering	<i>good</i>	
Three point hitch	<i>operational front and rear</i>	electrics, battery	<i>good</i>	
Transmission	<i>good</i>	Air system	<i>good</i>	
tools				
Make/ type		Make/ type		
Condition		Condition		
tires	% remaining	Size / Type	<i>cuts, recapped</i>	
front right	<i>20%</i>	<i>540/65R28</i>	<input type="checkbox"/>	<input type="checkbox"/>
front left	<i>20%</i>	<i>540/65R28</i>	<input type="checkbox"/>	<input type="checkbox"/>
rear right	<i>40%</i>	<i>650/65R38</i>	<input type="checkbox"/>	<input type="checkbox"/>
rear left	<i>50%</i>	<i>650/65R38</i>	<input type="checkbox"/>	<input type="checkbox"/>
Additional attachments:				
Problems, details:	<i>Belgian registration documents OK</i>			
<i>Tires : Goodyear Optitrac DT818</i>				
<i>Minor traces of oil next to turbo.</i>				
<i>Tractor is in good condition without major issues or problems. Ready to use.</i>				
dimensions for transport L x W x H in meter:	<i>5,50 x 2,70 x 3,10 m</i>			